Oil Field Environmental Incident Summary

Responsible Party: CORINTHIAN EXPLORATION (USA) CORP **Well Operator:** CORINTHIAN EXPLORATION (USA) CORP

Well Name: CORINTHIAN STARLEAF 12-32 1-H

Field Name: NORTHEAST LANDA Well File #: 26349

Date Incident: 3/31/2014 Time Incident: 17:30 Facility ID Number:

County: BOTTINEAU Twp: 164 Rng: 78 Sec: 32 Qtr: SE NW

Location Description: There was a north wind which sprayed the overflowing tank volume

(estimated 0.5 bbl) of crude immediately south of the lease.

Submitted By: Patrick Gratton Received By:

Contact Person: Patrick Gratton

STE 230, 323-10TH AVE SW CALGARY, AB T2R 0A5

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building: 3 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 0.5 Barrels 0.5 Barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Low

Areal Extent:

20 feet wide by 50 feet long of a light mist.

Potential Environmental Impacts:

Oil was cleaned immediately with bobcats and contaminated soil was sent for disposal. Spill was cleaned within three hours.

Action Taken or Planned:

Incident will be fully reviewed with the oil hauling company, field personnel, and office staff. Procedures to mitigate future occurrences will be put in place.

Wastes Disposal Location: Third party waste disposal

Agencies Involved:

Updates

Date: 5/23/2014 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 6/26/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 6/26/2014.

No sign of spill at the described location. Vegetation in the impact area is doing well with no signs of negative impact.

No followup is necessary.